

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:WallingfordJonniB@cdmsmith.com)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:SheldrakeSean@epa.gov)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:ZhenDavis@epa.gov)
CC: younghs@cdmsmith.com
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:ScottCoffey@cdmsmith.com)
Date: 7/26/2018 12:36:20 PM
Subject: Fish acoustic update
Attachments: [Snapchat-147066579.jpg](#)

Included is a photo of PID-AR-A29/RM 11.4. The data has been downloaded and buoy mooring was lowered back into the river using a davit over the side of the Next Generation vessel.

NRC is having difficulty locating PID-AR-A31 acoustic receiver, and after an hour of searching, the crew has decided to pursue other receivers for today. The crew will return later using a Pike pull to catch the buoy line and retrieve acoustic receiver.

Jonni

(b) (6)

Get Outlook for Android<<https://aka.ms/ghei36>>